

H-13078- 2013 Kenworth T800 Daycab Work Order History

March, 2022- Engine Repair, 685,030km.
Replace #6 Cylinder liner, piston & connecting rod
Replace main crankshaft & connecting rod bearings
Replace head & camshaft
Replace turbo, water pump & cooling lines

August, 2022- Engine Repair
Update ECM to 550hp

September, 2022- Engine Repair
Test all injectors, replace (5) injectors

November, 2022- Repair, 709,123km
Replace clutch brake

December, 2022 Engine Service, 714,212km.
Full engine service

November, 2023 Repair, 729,806km.
Perform safety inspection
Replace hood hinge and damper kit
Remove wheel ends on 1st & 2nd drive axles
Replace brake shoes, drums & hardware on LH 1st & 2nd drive axles
Replace axle seals on steering
Replace rear yoke bearing and seal on transmission
Replace transmission temperature sensor
Replace front slip yoke, driveshaft hanger bearing & (1) U-joint
Replace temperature sensor on rear drive axle
Replace (6) air springs, (6) KW air hose kits and (4) service kits
Replace (4) shock absorbers on drive axles
Replace RH 2nd drive axle shock absorber
Replace (4) gladhands
Replace power steering reservoir tank bracket, hoses & fluid
Install new 10lb fire extinguisher & cover
Install (4) new batteries
Replace LH driver's seat belt assembly
Replace cab filter
Replace LH windshield
Replace rear mudflaps
Replace front cab mounts
Replace cab airride height control valve
Replace fuel filter assembly & filter
Replace dash fuel gauge, fuel tank cap, fuel level sender and harness
Replace 5th wheel dash air slide switch
Replace air con compressor, dryer, condenser and HVC assembly
Replace air conditioning low- & high-pressure valves
Recharge air conditioning system
Repair front LH & RH hood fender cracks and refinish