



Vehicle History Report #: 55761704
Report Date: August 26, 2024 | 2:45 p.m. EDT
Report Status: Complete
Reference: ED202431557

2015 RAM 1500 SPORT

Pickup | 8 Cylinders | Gas
1C6RR7MT0FS771086
Country of Assembly: United States
Last Reported Odometer: 76,880 KM

One Owner™ > No Reported Accidents™ >



No Accident/Damage Records Found



Last Registered In: Alberta (Normal)



1 Service Record Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 26, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Alberta** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2022 Apr 12	76,880 KM	Jiffy Lube - Spruce Grove Spruce Grove, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedOil and filter changedAntifreeze/coolant checkedAir filter checked



Open Recalls

Recall #: R59 | LEFT REAR AXLE SHAFT Recall Date: 2015 Nov 17

Recall Description

THE LEFT AXLE SHAFT MAY NOT HAVE BEEN HEAT TREATED PROPERLY AT THE AXLE SHAFT BEARING JOURNAL. AN IMPROPERLY HEAT TREATED AXLE SHAFT MAY CAUSE THE BEARING TO CREATE A GRINDING NOISE DURING OPERATION, ILLUMINATE THE ANTI LOCK BRAKE SYSTEM (ABS) WARNING LAMP AND EVENTUALLY AN AXLE SHAFT FRACTURE.

Remedy

THE LEFT REAR AXLE SHAFT MUST BE INSPECTED ON ALL INVOLVED VEHICLES. VEHICLES FOUND WITH A SUSPECT AXLE SHAFT, BUT NOT A FAILED AXLE SHAFT, WILL HAVE THE AXLE SHAFT REPLACED. IF THE REAR AXLE INSPECTION DETERMINES THAT THE AXLE SHAFT HAS FAILED, THE REAR AXLE ASSEMBLY MUST BE REPLACED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: U61 | REPROGRAM POWERTRAIN CONTROL MODULE Recall Date: 2018 Jun 26

Recall Description

The fault handling strategy of the Engine Control Module (ECM) or PCM software in the affected vehicles does not remove positive torque requests from the engine controller if the CAN-C bus stops communicating while the cruise control is requesting positive torque.

Remedy

Inspect the software level of the ECM/PCM and, if necessary, perform a software flash on the ECM/PCM of affected vehicles to improve the fault handling so that if the CAN-C bus does stop communicating any active torque requests will be cleared

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: U74 | 2015 - 2017 TAILGATE LATCH Recall Date: 2018 Aug 03

Recall Description

The tailgate actuator limiter tab within the power lock actuator control assembly may fracture allowing the lock rod control bracket to over-travel which may pull the lock rods and release the latches, potentially resulting in the tailgate inadvertently falling open at any time

Remedy

The remedy for this item will limit the locking actuator travel and not allow the pivot arm from overtraveling and pulling on the locking/unlocking rods

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: Y55 | 2015-2020 DS SABIC Inflator Recall Date: 2021 Aug 27

Recall Description

A SABIC inflator rupture may result in compressed gas rapidly escaping from the inflator and material potentially being propelled into the vehicle.

Remedy

FCA US will conduct a voluntary safety recall on all affected vehicles. For vehicles in Recall ID Y55, FCA US will replace one or both SABIC's.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

**Stolen Vehicle Check**

✔ This vehicle is not actively declared stolen.

**Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Oct 1		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as medium blue
2015 Nov 17		RAM	Recall	Manufacturer Recall Issued Recall # R59
2016 May 10		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium blue
2018 May 31		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium blue
2018 Jun 26		RAM	Recall	Manufacturer Recall Issued Recall # U61
2018 Aug 3		RAM	Recall	Manufacturer Recall Issued Recall # U74
2020 May 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as medium blue
2021 Aug 27		RAM	Recall	Manufacturer Recall Issued Recall # Y55
2022 Apr 12	76,880 KM	Jiffy Lube - Spruce Grove Spruce Grove, Alberta, Canada	Service Record	Vehicle serviced
2022 May 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as medium blue
2023 Jun 1		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as medium blue
2024 May 11		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as medium blue



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.

